

PRAIRIE DU SAC

SAUK-PRAIRIE (91C) 2 W UTC-6(-5DT) N43°17.87' W89°45.35'

832 B NOTAM FILE GRB

RWY 18-36: H2936X60 (ASPH) MIRL 0.4% up N

RWY 18: REIL. PAPI(P2L)—GA 3.0° TCH 26'. Pole.

RWY 36: REIL. PAPI(P2L)—GA 3.0° TCH 26'. Tree.

SERVICE: S4 FUEL, UL94 LGT ACTIVATE MIRL Rwy 18-36; REIL

Rwys 18 and 36; PAPI Rwy 18 and Rwy 36—CTAF.

AIRPORT REMARKS: For svcs ctc arpt manager at 608-577-3754.

Ultralight activity on and invof arpt. Tkofs and lds are prohibited on unpaved sfcs. Maintenance vehicle tfc on and invof arpt. West ramp and twy pvt, clsd transient. Avoid hospital/helipad 3,000' southeast of Rwy 36 thld. Rwy 18 depts climb to 1,800' MSL on rwy heading before turning east/southeast.

AIRPORT MANAGER: 608-577-3754

COMMUNICATIONS: CTAF 122.9

® MADISON APP/DEP CON 135.45 (1200-0500Z±)

® CHICAGO CENTER APP/DEP CON 133.3 (Hours madison apch clsd)

CLEARANCE DELIVERY PHONE: For CD ctc Chicago ARTCC at 630-906-8921.

RADIO AIDS TO NAVIGATION: NOTAM FILE DLL.

DELLS (H) VORTAC 117.0 DLL Chan 117 N43°33.05'

W89°45.82' 176° 15.2 NM to fld. 1023/3E.


VOR unusable:

103°-114° byd 30 NM blo 17,000'

CHICAGO

L-28G

IAP



PRENTICE (5N2) 1 E UTC-6(-5DT) N45°32.30' W90°16.58'

1579 B NOTAM FILE GRB

RWY 09-27: H3134X60 (ASPH) MIRL 0.4% up E

RWY 09: Thld dsplcd 337'. Railroad.

RWY 27: Road.

SERVICE: LGT ACTIVATE MIRL Rwy 09-27 & twy lgts—CTAF.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 715-360-2000

COMMUNICATIONS: CTAF/UNICOM 123.0

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE RHI.

RHINELANDER (L) VOR/DME 109.2 RHI Chan 29 N45°38.03'

W89°27.47' 259° 35.0 NM to fld. 1599/2E. HIWAS.

VOR unusable:

171°-228° byd 10 NM

310°-340° byd 20 NM blo 5,000'


DME unusable:

265°-280°

330°-335° byd 25 NM blo 5,000'

GREEN BAY

L-141



PRICE CO (See PHILLIPS on page 365)